



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 49524

Inspection Report

Project Name: 5138 Oak Island Road - COBI

Date: 04/14/2015 Any any

Address: 5138 Oak Island Road - COBI ,Belle Isle, Orange County, FL

Permit No: 2015-04-019

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1300215.0000

Contact: Marty Osteen at 386-736-4220

Scope of Inspection: Rough Plumbing Inspection

Inspection Type: **See Scope**

Disposition of Inspection: **Pass**

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Les Rutherford, BN 4564