



UNIVERSAL ENGINEERING SCIENCES, INC.

3532 Maqqie Boulevard
Orlando, FL 32811
Phone: 407-581-8161 Fax: 407-581-0313

Work Order No.49187

Inspection Report

Project Name: 5138 Oak Island Road - COBI
Address: 5138 Oak Island Road - COBI ,Belle Isle, Orange
County, FL
Client: City of Belle Isle
ProjectNo.: 0115.1300215.0000

Date: 04/07/2015 Any any
Permit No.: 2014-10-025
Lot No.:
Contact: Joe Hennessy at 386-547-9538

Scope of Inspection: Stemwall Inspection

Inspection Type: See Scope

Disposition of Inspection: Pass

Comments:

I hereby affirm that to the best of my knowledge and believe, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector : William Moody, BN4489