



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 49456

Inspection Report

Project Name: 5210 Oak Island Road ~ COBI

Date: 04/13/2015 Any am

Address: 5210 Oak Island Road ~ COBI ,Belle Isle, Orange County, FL

Permit No: 2015-03-045

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1500551.0000

Contact: Keith Severns at 407-851-7730

Scope of Inspection: Post SWO per City Manager; contractor did not install silt fencing & removed trees without a permit.
Take pictures & send to BIDresults@universalengineering.com.

Inspection Type: See Scope

Disposition of Inspection: Complete

Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
04/13/2015	Posted SWO on permit box indicating requirement of permits needed, took pictures.	Luis Colon

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Luis Colon, BN3362