



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 50269

Inspection Report

Project Name: 5238 Jade Circle ~ COBI

Date: 04/27/2015 Any any

Address: 5238 Jade Circle ~ COBI ,Belle Isle, Orange County, FL

Permit No: 2015-04-051

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1500661.0000

Contact: John byrne at 407 922 0500

Scope of Inspection: Roof dry-in/flashing inspection for flat bitumen roof


Inspection Type: See Scope

Disposition of Inspection: Pass

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Luis Colon, BN3362



Luis A. Colon