



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 49957

Inspection Report

Project Name: 5296 Chiswick Circle - COBI
Address: 5296 Chiswick Circle - COBI ,Belle Isle, Orange County, FL
Client: City of Belle Isle
ProjectNo.: 0115.1400571.0000

Date: 04/21/2015 Any any
Permit No: 2015-12-094
Lot No.:
Contact: Candace Strausheim at 407-847-9322

Scope of Inspection: Final Building Inspection for pool

Inspection Type: See Scope

Disposition of Inspection: Fail

Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
04/21/2015	1. must pass electric final. 2. rear gate locked cannot verify self closing and latching requirement. 3. side gate does NOT self close or latch, life safety violation.	Leslie Rutherford

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Les Rutherford, BN 4564