



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 49958

Inspection Report

Project Name: 5296 Chiswick Circle - COBI
Address: 5296 Chiswick Circle - COBI ,Belle Isle, Orange County, FL
Client: City of Belle Isle
ProjectNo.: 0115.1400571.0000

Date: 04/21/2015 Any any
Permit No: 2015-12-095
Lot No.:
Contact: Candace Strausheim at 407-847-9322

Scope of Inspection: Final Electrical Inspection for pool

Inspection Type: See Scope

Disposition of Inspection: Fail

Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
04/21/2015	pool pump not bonded, no site documentation to show if double insulated. Violation of 2008 NEC 680.26.B.6	Leslie Rutherford

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Les Rutherford, BN 4564