



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 49959

Inspection Report

Project Name: 5296 Chiswick Circle - COBI

Address: 5296 Chiswick Circle - COBI ,Belle Isle, Orange County, FL

Client: City of Belle Isle

ProjectNo.: 0115.1400571.0000

Date: 04/21/2015 Any any

Permit No: 2015-12-096

Lot No.:

Contact: Candace Strausheim at 407-847-9322

Scope of Inspection: Final Plumbing Inspection for pool

Inspection Type: See Scope

Disposition of Inspection: Pass

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Les Rutherford, BN 4564