



UNIVERSAL ENGINEERING SCIENCES, INC.

3532 Maqqie Boulevard
Orlando, FL 32811
Phone: 407-581-8161 Fax: 407-581-0313

Work Order No.49101

Inspection Report

Project Name: 5296 Chiswick Circle - COBI
Address: 5296 Chiswick Circle - COBI ,Belle Isle, Orange
County, FL
Client: City of Belle Isle
ProjectNo.: 0115.1400571.0000

Date: 04/03/2015 Any am
Permit No.: 2015-12-094
Lot No.:
Contact: Candace Strausheim at 407-847-9322

Scope of Inspection: Pool Safety Inspection

Inspection Type: See Scope

Disposition of Inspection: Pass

Comments:

I hereby affirm that to the best of my knowledge and believe, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector : Luis Colon, BN3362