



UNIVERSAL ENGINEERING SCIENCES, INC.

3532 Maqqie Boulevard
Orlando, FL 32811
Phone: 407-581-8161 Fax: 407-581-0313

Work Order No.48906

Inspection Report

Project Name: 5435 Ming Drive - COBI
Address: 5435 Ming Drive - COBI ,Belle Isle, Orange County,
Client: City of Belle Isle
ProjectNo.: 0115.1500029.0000

Date: 03/31/2015 Any any
Permit No.: 2015-01-046
Lot No.:
Contact: Vic Norberg at 407-947-9097

Scope of Inspection: Final alarm Inspection for pool

Inspection Type: See Scope

Disposition of Inspection: Pass

Comments:

03/31/2015 windows and doors alarm final.

Luis Colon

I hereby affirm that to the best of my knowledge and believe, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector : Luis Colon, BN3362