



UNIVERSAL ENGINEERING SCIENCES, INC.

3532 Maqqie Boulevard
Orlando, FL 32811
Phone: 407-581-8161 Fax: 407-581-0313

Work Order No.48905

Inspection Report

Project Name: 5435 Ming Drive - COBI

Date: 03/31/2015 Any any

Address: 5435 Ming Drive - COBI ,Belle Isle, Orange County,

Permit No.: 2015-01-047

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1500029.0000

Contact: Vic Norberg at 407-947-9097

Scope of Inspection: Final Electrical Inspection for pool

Inspection Type: See Scope

Disposition of Inspection: Pass

Comments:

I hereby affirm that to the best of my knowledge and believe, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector : Luis Colon, BN3362