



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 50033

Inspection Report

Project Name: 5437 Pasadena Drive - COBI

Date: 04/22/2015 Any am

Address: 5437 Pasadena Drive - COBI ,Belle Isle, Orange County, FL

Permit No: 2015-03-009

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1400554.0000

Contact: Albert Cichra at 407-468-9039

Scope of Inspection: Roof Sheathing Inspection for boathouse

Inspection Type: **See Scope**

Disposition of Inspection: **Pass**

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: William Moody, BN4489