



# UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences  
Geophysical Services • Materials Testing • Threshold Inspection  
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 49894

## Inspection Report

Project Name: 6526 Saint Partin Place ~ COBI

Date: 04/17/2015 Any any

Address: 6526 Saint Partin Place ~ COBI ,Belle Isle, Orange County,  
FL

Permit No: 2015 04 037

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1500636.0000

Contact: Susan Manchester at 407 581  
8161

Scope of Inspection: REVIEW mechanical app for one 5ton change-out

Inspection Type: See Scope

Disposition of Inspection: Complete

### Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
04/19/2015	Review complete	Richard Olds

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Richard Olds, BN 4406