



# UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences  
Geophysical Services • Materials Testing • Threshold Inspection  
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 50035

## Inspection Report

Project Name: 6731 Matchett Road - COBI

Date: 04/21/2015 Any any

Address: 6731 Matchett Road ,Belle Isle, Orange County, FL

Permit No: 2015-04-046

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1300086.0000

Contact: Susan Manchester at 407 581 8161

Scope of Inspection: REVIEW mechanical permit app for one 2-ton change out

Inspection Type: See Scope

Disposition of Inspection: Complete

### Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
04/21/2015	Approved per Don Moody	Susan Manchester

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: William Moody, BN4489