



UNIVERSAL ENGINEERING SCIENCES, INC.

3532 Maqqie Boulevard
Orlando, FL 32811
Phone: 407-581-8161 Fax: 407-581-0313

Work Order No.48908

Inspection Report

Project Name: 6902 Daetwyler Drive ~ COBI
Address: 6902 Daetwyler Drive ~ COBI ,Belle Isle, Orange
Client: ^{County, FL} City of Belle Isle
ProjectNo.: 0115.1500069.0000

Date: 03/31/2015 Any any
Permit No.: 2015-02-047
Lot No.:
Contact: Hugo at 321-295-3083

Scope of Inspection: Final Roof Inspection

Inspection Type: See Scope

Disposition of Inspection: Pass

Comments:

I hereby affirm that to the best of my knowledge and believe, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector : Luis Colon, BN3362