



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 49789

Inspection Report

Project Name: 7204 Seminole Drive ~ COBI

Date: 04/16/2015 Any pm

Address: 7204 Seminole Drive ~ COBI, Belle Isle, Orange County, FL

Permit No: 2015-03-006

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1500082.0000

Contact: Dale Thomas at 321-863-1984

Scope of Inspection: Underground Plumbing Inspection


Inspection Type: **See Scope**

Disposition of Inspection: **Pass**

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Luis Colon, BN3362



Luis A. Colon