



# UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences  
Geophysical Services • Materials Testing • Threshold Inspection  
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 50206

## Inspection Report

Project Name: 7204 Seminole Drive ~ COBI

Date: 04/24/2015 Any any

Address: 7204 Seminole Drive ~ COBI ,Belle Isle, Orange County, FL

Permit No: 2015-03-006

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1500082.0000

Contact: Dale Thomas at 321 863 1984

Scope of Inspection: Tub set Inspection

Inspection Type: See Scope

Disposition of Inspection: Fail

### Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
04/24/2015	no permit or APPROVED plan on site. NOTE: tubset needs tub filled and drain through slab sealed in a code compliant manner.	Leslie Rutherford

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Les Rutherford, BN 4564