



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 49437

Inspection Report

Project Name: 7319 Matchett Road - COBI

Address: 7319 Matchett Road - COBI ,Belle Isle, Orange County, FL

Client: City of Belle Isle

ProjectNo.: 0115.1500036.0000

Scope of Inspection: Foundation Inspection

Inspection Type: **See Scope**

Date: 04/13/2015 Any any

Permit No: 2015-02-010

Lot No.:

Contact: Dorothy Hall at 407-851-0680

Disposition of Inspection: Fail

Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
04/13/2015	* u/g electrical conduit inspection required * 3" clearance around steel rebar in footer required * compaction report missing .	Luis Colon

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Luis Colon, BN3362