



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 50184

Inspection Report

Project Name: 7425 Lake Drive- COBI

Date: 04/24/2015 Any any

Address: 7425 Lake Drive ,Belle Isle, Orange County, FL

Permit No: 2015-02-036

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1300595.0000

Contact: Jim at 407-948-6234

Scope of Inspection: Rough Electrical Inspection

Inspection Type: **See Scope**

Disposition of Inspection: Pass

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Les Rutherford, BN 4564