



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 50230

Inspection Report

Project Name: 7425 Lake Drive- COBI

Date: 04/27/2015 Any any

Address: 7425 Lake Drive ,Belle Isle, Orange County, FL

Permit No: 2015-04-032

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1300595.0000

Contact: Rob Frazier at 407-353-1942

Scope of Inspection: Gas Rough-in Inspection

Inspection Type: See Scope

Disposition of Inspection: Fail

Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
04/27/2015	pressure test on interior piping required * pipe bonding required * PE underground pipe pressure test required * tracer wire for PE pipe required * burial depth 12" required * 406.4.1 2411.1.1 404.15.3 404.10	Luis Colon

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Luis Colon, BN3362