



# UNIVERSAL ENGINEERING SCIENCES, INC.

3532 Maqqie Boulevard  
Orlando, FL 32811  
Phone: 407-581-8161 Fax: 407-581-0313

Work Order No.49125

## Inspection Report

Project Name: 7425 Lake Drive- COBI

Date: 04/07/2015 Any any

Address: 7425 Lake Drive ,Belle Isle, Orange County, FL

Permit No.: 2015-12-022

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1300595.0000

Contact: Maurice Sass at 407-466-0218

Scope of Inspection: Sheathing Inspection (roof)

**Inspection Type:** See Scope

**Disposition of Inspection:** Pass

### Comments:

I hereby affirm that to the best of my knowledge and believe, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector : William Moody, BN4489