



UNIVERSAL ENGINEERING SCIENCES, INC.

3532 Maqqie Boulevard
Orlando, FL 32811
Phone: 407-581-8161 Fax: 407-581-0313

Work Order No.49124

Inspection Report

Project Name: 7425 Lake Drive- COBI
Address: 7425 Lake Drive ,Belle Isle, Orange County, FL
Client: City of Belle Isle
ProjectNo.: 0115.1300595.0000

Date: 04/07/2015 Any any
Permit No.: 2015-12-022
Lot No.:
Contact: Maurice Sass at 407-466-0218

Scope of Inspection: Sheathing Inspection (walls)

Inspection Type: See Scope

Disposition of Inspection: Pass

Comments:

I hereby affirm that to the best of my knowledge and believe, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector : William Moody, BN4489