



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 66294

Inspection Report

Project Name:	1621 Wind Harbor Road ~ COBI	Date:	04/07/2016 Any any
Address:	1621 Wind Harbor Road ~ COBI ,Belle Isle, Orange County, FL	Permit No:	2016-03-025
Client:	City of Belle Isle	Lot No.:	
ProjectNo.:	0115.1600211.0000-0115-01	Contact:	Collina Gast at 407-581-8161

Scope of Inspection: Investigate plumbing work without a permit. Contractor submitted a plumbing application for Repipe; it was approved however they then requested we void the permit. Homeowner was called on 04/05/16 to ascertain if the work was completed; there was no answer so a voicemail was left. If evidence is present, please post a SWO on the residence.

Inspection Type: See Scope

Disposition of Inspection: Pass

Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
04/07/2016	Owner pulled permit 4/7/2016	Karl McGuire

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Karl McGuire, BN5498