



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 66958

Inspection Report

Project Name: 1646 Wind Willow Road ~ COBI

Date: 04/27/2016 Any pm

Address: 1646 Wind Willow Road ~ COBI, Belle Isle, Orange County,
FL

Permit No: 2016-03-023

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1600196.0000-0115-02

Contact: Tom Davy at 407-484-5239

Scope of Inspection: Final Building Inspection for Windows

Inspection Type: See Scope

Disposition of Inspection: Pass

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Karl McGuire, BN5498