



# UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences  
Geophysical Services • Materials Testing • Threshold Inspection  
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 66333

## Inspection Report

Project Name: 1722 Hoffner Avenue - COBI	Date: 04/07/2016 Any any
Address: 1722 Hoffner Avenue ,Belle Isle, Orange County, FL	Permit No: 2016-03-065
Client: City of Belle Isle	Lot No.:
ProjectNo.: 0115.1300050.0000-0115-01	Contact: Jessica Graf at 407-851-0680
Scope of Inspection: Roof Covering In-Progress Inspection	
Inspection Type: See Scope	

Disposition of Inspection: Pass

### Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
04/08/2016	Per Karl: not completely finishe yet	Collina Gast
04/08/2016	This inspection only partially passed due to an issue with the flashing. Karl is re-inspecting the flashing today.	Susan Manchester
04/08/2016	The in-progress is a PASS. It is the first inspection that was a partial.	Susan Manchester

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Karl McGuire, BN5498