



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 66519

Inspection Report

Project Name: 1804 Wind Willow Road - COBI

Date: 04/13/2016 Any any

Address: 1804 Wind Willow Road - COBI ,Belle Isle, Orange County,
FL

Permit No: 2016-02-025

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1500037.0000-0115-03

Contact: Gary Parliament at 386-344-4592

Scope of Inspection: Rough Plumbing Pipe Inspection for Pool

Inspection Type: **Plumbing - Rough In**

Disposition of Inspection: **Pass**

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Karl McGuire, BN5498