



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 66422

Inspection Report

Project Name: 1808 Swann Avenue - COBI

Address: 1808 Swann Avenue - COBI ,Belle Isle, Orange County, FL

Client: City of Belle Isle

ProjectNo.: 0115.1501054.0000-0115-02

Scope of Inspection: In-Progress Window Inspection

Inspection Type: **See Scope**

Date: 04/11/2016 Any pm

Permit No: 2016-03-045

Lot No.:

Contact: Luke at 407-636-1368

Disposition of Inspection: Fail

Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
04/11/2016	windows bucks not per NOA (full with) Windows not shimed at fasners	Dewey Anderson

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Dewey Anderson, BN735