



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 66001

Inspection Report

Project Name: 1811 Wind Harbor Road - COBI

Date: 04/01/2016 Any am

Address: 1811 Wind Harbor Road - COBI, Belle Isle, Orange County,
FL

Permit No: 2016-01-005

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1300116.0000-0115-03

Contact: Marisol Mojica at 407-261-2277

Scope of Inspection: Final Building Inspection for 10 size-for-size windows

Inspection Type: See Scope

Disposition of Inspection: Pass

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Karl McGuire, BN5498