



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 66773

Inspection Report

Project Name: 1900 McCoy Road ~ COBI (commercial)

Date: 04/20/2016 Any any

Address: 1900 McCoy Road ~ COBI, Belle Isle, Orange County, FL

Permit No: 2016-04-026

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1400497.0000-0115-12

Contact: Joe Mattingly at 407 462 6493

Scope of Inspection: Above-Ceiling Mechanical Inspection (ductwork)

Inspection Type: **Buidling Insulation**

Disposition of Inspection: **Pass**

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Karl McGuire, BN5498