



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 66446

Inspection Report

Project Name: 1934 McCoy Road ~ COBI commercial Woodspring
Suites Hotel

Date: 04/11/2016 11:30 am

Address: 1934 McCoy Road ~ COBI commercial , Belle Isle, Orange
County, FL

Permit No: 2016-03-006

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1501343.0000-0115-04

Contact: Troy Ernsthause at 419-960-
9071

Scope of Inspection: Fire Inspection - Underground Main Visual Inspection

Inspection Type: **See Scope**

Disposition of Inspection: **Pass**

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Fire Prevention Code.

Inspector: Lisa Whaley, 153187