



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 66520

Inspection Report

Project Name: 1934 McCoy Road ~ COBI commercial ~ Woodspring Suites

Date: 04/13/2016 Any any

Address: 1934 McCoy Road ~ COBI commercial , Belle Isle, Orange County, FL

Permit No: 2016-04-016

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1501343.0000-0115-06

Contact: Susan Manchester at 407 581 161

Scope of Inspection: REVIEW app for plumbing - 460 fixtures

Inspection Type: See Scope

Disposition of Inspection: Pass

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Dale Baker, BN 3927