3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 66613

Brandon Fies at 407 688 2657

04/14/2016 Any any

Date:

Lot No.: Contact:

Permit No: 2016-10-065

Inspection Report

Project Name: 1934 McCoy Road ~ COBI commercial ~ Woodspring

Suites

Address: 1934 McCoy Road ~ COBI commercial ,Belle Isle, Orange

County, FL

Client: City of Belle Isle

ProjectNo.: 0115.1501343.0000-0115-01

Scope of Inspection: Underground stormwater inspection for site development

Inspection Type: See Scope

Disposition of Inspection: Partial Pass

Comments:

Task DateTask NoteUser Name04/14/2016As highlited on plansDewey Anderson

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Dewey Anderson, BN735