



# UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences  
Geophysical Services • Materials Testing • Threshold Inspection  
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 66817

## Inspection Report

Project Name: 1934 McCoy Road ~ COBI commercial ~ Woodspring Suites

Date: 04/22/2016 Late am

Address: 1934 McCoy Road ~ COBI commercial, Belle Isle, Orange County, FL

Permit No: 2016-03-006

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1501343.0000-0115-04

Contact: Troy Ernsthause at 419-960-9071

Scope of Inspection: Fire Inspection ~ Fire Line inspection for the line running to the FDC connection and sprinkler riser

Inspection Type: **See Scope**

Disposition of Inspection: **Pass**

### Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Fire Prevention Code.

Inspector: Lisa Whaley, 153187