3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 66869

04/25/2016 Any any

Rick Weeks at 863-236-1110

Date:

Lot No .:

Contact:

Permit No: 2016-04-016

## **Inspection Report**

Project Name: 1934 McCoy Road ~ COBI commercial ~ Woodspring

Suites

Address: 1934 McCoy Road ~ COBI commercial, Belle Isle, Orange

County, FL

Client: City of Belle Isle

ProjectNo.: 0115.1501343.0000-0115-06

Scope of Inspection: Underground Plumbing Inspection

Inspection Type: See Scope

**Disposition of Inspection:** Pass

**Comments:** 

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: James Pappalardo, BN5706

James & Pappalardo