



# UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences  
Geophysical Services • Materials Testing • Threshold Inspection  
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 66310

## Inspection Report

Project Name: 2067 McCoy Road ~ COBI CONWAY BREEZE  
CONDOS

Date: 04/11/2016 Any any

Address: 2067 McCoy Road ~ COBI commercial , Belle Isle, Orange  
County, FL

Permit No: 2016-02-046

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1600142.0000-0115-01

Contact: Susan Manchester at 407 581  
8161

Scope of Inspection: REVIEW site development and GEO plans for Conway Breeze Condos - determine if any further  
action needed on UES behalf (COBI approved zoning)

Inspection Type: See Scope

Disposition of Inspection: Pass

### Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Matthew Rush, BN5145