



# UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences  
Geophysical Services • Materials Testing • Threshold Inspection  
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 66278

## Inspection Report

Project Name: 2319 Nela Ave - COBI

Date: 04/07/2016 Any am

Address: 2319 Nela Ave ,Belle Isle, Orange County, FL

Permit No: 2016-01-029

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1300212.0000-0115-02

Contact: Chris Haan at 321-303-0535

Scope of Inspection: Sheathing Inspection (roof)

Inspection Type: **See Scope**

Disposition of Inspection: **Pass**

### Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Karl McGuire, BN5498