



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 66512

Inspection Report

Project Name: 2319 Nela Ave - COBI

Date: 04/13/2016 Any any

Address: 2319 Nela Ave ,Belle Isle, Orange County, FL

Permit No: 2016-02-032

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1300212.0000-0115-03

Contact: Steve at 407-247-0393

Scope of Inspection: Water Pipe Inspection

Inspection Type: See Scope

Disposition of Inspection: Pass

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Karl McGuire, BN5498