



# UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences  
Geophysical Services • Materials Testing • Threshold Inspection  
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 66049

## Inspection Report

Project Name: 2323 McCoy Road ~ COBI~ Palm Square Condos (multi-family)

Date: 03/31/2016 Any any

Address: 2323 McCoy Road ~ COBI~ Palm Square Condos (multi-, Belle Isle, Orange County, FL

Permit No: 2016-10-022

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.0100403.0002-0115-52

Contact: Jonathan Rodriguez at 407-437-1599

Scope of Inspection: Bldg. 8, Unit 804 - Final Mechanical Inspection

Inspection Type: **See Scope**

Disposition of Inspection: Courtesy

### Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
03/31/2016	Cancelled Inspection	Karl McGuire

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Karl McGuire, BN5498