



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 66287

Inspection Report

Project Name: 2323 McCoy Road ~ COBI~ Palm Square Condos (multi-family)

Date: 04/07/2016 Any any

Address: 2323 McCoy Road ~ COBI~ Palm Square Condos (multi-
, Belle Isle, Orange County, FL

Permit No: 2015-12-081

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1400403.0001-0115-46

Contact: Sunia Piermont at 407-228-4645

Scope of Inspection: Bldg. 8, Unit 818 - Final Building Inspection for CO

Inspection Type: **See Scope**

Disposition of Inspection: **Pass**

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Karl McGuire, BN5498