



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 66789

Inspection Report

Project Name: 2510 Oak Island Pointe ~ COBI	Date: 04/27/2016 Any am
Address: 2510 Oak Island Pointe ~ COBI, Belle Isle, Orange County, FL	Permit No: 2016-04-007
Client: City of Belle Isle	Lot No.:
ProjectNo.: 0115.1600265.0000-0115-01	Contact: Jackie Stelling at 407-788-9900
Scope of Inspection: Final Mechanical Inspection	
Inspection Type: See Scope	

Disposition of Inspection: Fail

Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
04/27/2016	Failed Inspection....called contractor...no one home..no access for inspection	Karl McGuire

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Karl McGuire, BN5498