



# UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences  
Geophysical Services • Materials Testing • Threshold Inspection  
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 66789

## Inspection Report

Project Name: 2510 Oak Island Pointe ~ COBI

Address: 2510 Oak Island Pointe ~ COBI, Belle Isle, Orange County, FL

Client: City of Belle Isle

ProjectNo.: 0115.1600265.0000-0115-01

Scope of Inspection: Final Mechanical Inspection

Inspection Type: See Scope

Date: 04/27/2016 Any am

Permit No: 2016-04-007

Lot No.:

Contact: Jackie Stelling at 407-788-9900

Disposition of Inspection: Fail

### Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
04/27/2016	Failed Inspection....called contractor...no one home..no access for inspection	Karl McGuire

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Karl McGuire, BN5498