



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 66311

Inspection Report

Project Name: 4118 Isle Vista Avenue ~ COBI

Date: 04/11/2016 Any any

Address: 4118 Isle Vista Avenue ~ COBI ,Belle Isle, Orange County, FL

Permit No: 2016-03-059

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1600228.0000-0115-02

Contact: Susan Manchester at 407 581 8161

Scope of Inspection: REVIEW zoning approved SFR plans

Inspection Type: See Scope

Disposition of Inspection: Fail

Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
04/11/2016	1- R315.1 need carbon monoxide detectors within 10 feet of all bedroom doors. 2- Electrical notes references NEC 2008, needs to be NEC 2011. 3- Sheet S2 on roof nailing pattern it calls for 8D common nails, need to use 8D ring shank nails per R803.2.3.1	Matthew Rush

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Matthew Rush, BN5145