3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 66566

## **Inspection Report**

Inspection	Type:	See Scope		
	_			
Scope of In	spection:	Final Mechanical Inspection		
ProjectNo.:	0115.14	400232.0000-0115-02	Contact:	Cynthia Durham at 407.282.5000
Client:	Client: City of Belle Isle		Lot No.:	
Address:	ress: 4234 Kezar Court ~ COBI ,Belle Isle, Orange County, FL			2016-03-06
Project Name: 4234 Kezar Court ~ COBI			Date:	04/15/2016 Any any

**Disposition of Inspection:** Pass

## **Comments:**

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Karl McGuire, BN5498

Kail 2. Me Hum