



# UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences  
Geophysical Services • Materials Testing • Threshold Inspection  
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 66883

## Inspection Report

Project Name: 5024 Louvre Avenue ~ COBI

Date: 04/25/2016 Any any

Address: 5024 Louvre Avenue ~ COBI, Belle Isle, Orange County, FL

Permit No: 2016-04-031

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1600289.0000-0115-01

Contact: Nicole at 407-770-0322

Scope of Inspection: Final Electrical Inspection

Inspection Type: **Plumbing - Underground DWV**

Disposition of Inspection: **Pass**

### Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: James Pappalardo, BN5706