



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 66941

Inspection Report

Project Name: 5102 Darden Avenue ~ COBI

Date: 04/26/2016 Any am

Address: 5102 Darden Avenue ~ COBI, Belle Isle, Orange County, FL

Permit No: 2016-12-003

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1501457.0000-0115-01

Contact: Karen Cunningham at (407)774-9850

Scope of Inspection: Final Plumbing Inspection

Inspection Type: **Plumbing - Final**

Disposition of Inspection: **Pass**

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: James Pappalardo, BN5706