



# UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences  
Geophysical Services • Materials Testing • Threshold Inspection  
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 66555

## Inspection Report

Project Name: 5130 S. Conway Road ~ COBI Commercial Planet  
Fitness

Address: 5130 S. Conway Road ~ COBI ,Belle Isle, Orange County,  
FL

Client: City of Belle Isle

ProjectNo.: 0115.1600278.0000-0115-01

Date: 04/13/2016 Any any

Permit No: 2016-04-017

Lot No.:

Contact: Susan Manchester at 407 581  
8161

Scope of Inspection: REVIEW building app for sign permit

Inspection Type: **See Scope**

Disposition of Inspection: Pass

### Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Dale Baker, BN 3927