



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 65970

Inspection Report

Project Name: 5174 S. Conway Road ~ COBI commercial

Date: 03/31/2016 Any any

Address: 5174 S. Conway Road ~ COBI commercial ,Belle Isle,
Orange County, FL

Permit No: 2016-03-028

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1600216.0000-0115-02

Contact: Brittany Porter at 407-482-8332

Scope of Inspection: Final Plumbing Inspection

Inspection Type: See Scope

Disposition of Inspection: Pass

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Karl McGuire, BN5498