



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 66098

Inspection Report

Project Name: 6600 Saint Partin Place ~ COBI

Date: 04/01/2016 Any any

Address: 6600 Saint Partin Place ~ COBI, Belle Isle, Orange County,
FL

Permit No: 2016-04-003

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1600256.0000-0115-01

Contact: Susan Manchester at 407 581
8161

Scope of Inspection: REVIEW app for re-pipe

Inspection Type: **See Scope**

Disposition of Inspection: Pass

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Dale Baker, BN 3927