



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 66515

Inspection Report

Project Name: 7008 Willoughby Lane ~ COBI
Address: 7008 Willoughby Lane ~ COBI ,Belle Isle, Orange County, FL
Client: City of Belle Isle
ProjectNo.: 0115.1500803.0000-0115-05

Date: 04/13/2016 Any any
Permit No: 2016-03-044
Lot No.:
Contact: Susan Manchester at 407 581 8161

Scope of Inspection: RE-REVIEW app for pool enclosure - req PA's for roof panels arrived

Inspection Type: See Scope

Disposition of Inspection: Pass

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Dale Baker, BN 3927