



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 66280

Inspection Report

Project Name: 7145 Lake Drive ~ COBI

Date: 04/07/2016 Any any

Address: 7145 Lake Drive ~ COBI ,Belle Isle, Orange County, FL

Permit No: 2016-04-005

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1501547.0000-0115-04

Contact: Susan Manchester at 407 581
8161

Scope of Inspection: REVIEW roof app for pavilion

Inspection Type: See Scope

Disposition of Inspection: Pass

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Dale Baker, BN 3927