



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 66543

Inspection Report

Project Name: 7145 Lake Drive ~ COBI

Date: 04/13/2016 Any any

Address: 7145 Lake Drive ~ COBI ,Belle Isle, Orange County, FL

Permit No: 2016-12-042

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1501547.0000-0115-01

Contact: Jaime Bojanowski at 407-733-2067

Scope of Inspection: Exterior Wall Sheathing Inspection

Inspection Type: **Building - Sheathing**

Disposition of Inspection: **Pass**

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Karl McGuire, BN5498